Oil Field Environmental Incident Summary

Responsible Party: EOG RESOURCES, INC. **Well Operator:** EOG RESOURCES, INC.

Well Name: PARSHALL 49-2226H

Field Name: PARSHALL Well File #: 27159

Date Incident: 4/7/2015 Time Incident: 08:30 Facility ID Number:

County: MOUNTRAIL Twp: 152 Rng: 90 Sec: 22 Qtr: NW NE

Location Description:

Submitted By: Keith Kallberg Received By:

Contact Person: Keith Kallberg

600 17TH ST STE 1000N DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units
40 Barrels 40 Barrels 40 barrels

Brine Other

Oil

Description of Other Released Contaminant:

Inspected: Written Report Received: 4/10/2015 Clean Up Concluded: 4/9/2015

Risk Evaluation:

Low

Areal Extent:

Potential Environmental Impacts:

Low

Action Taken or Planned:

The valve by the sight glass was closed stopping the release, vac trucks were brought in and removed the free fluids and a cleanup crew will use a hydro excavator to remove the affected material inside the containment and a mini excavator and skidsteer for outside the containment.

Wastes Disposal Location: Recovered oil put back into a tank onsite and solids will be taken to

Clean Harbors.

Agencies Involved: TAT and MHA

Updates

Date: 4/8/2015 Status: Reviewed - Assigned to Other Agency Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release remained on location according to the report. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.